

REPORT of SURVEY for REPAIRS.

No. ³³⁷ Survey held at London Date March 26 1889
 on the Barque Marguerite of Huntley Master Mottley
 Tonnage 563 Built at Aberdeen When built 1804
 By whom built _____ Owners Chapman & Co.
 Port belonging to London Destined Voyage East
 If Surveyed Afloat or in Dry Dock Invoked Dry Dock

Original Survey, No. 545,1249, Dated March 1888 Classed A. 1
2602, 3208, 4015,
 Port London

Repairs at the present time stripped caulks throughout
to bale to re-caulk with yellow metal to 13 feet

The general condition of this ship is very
good

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>4th 573. 1839</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions

In my opinion this ship is fully entitled to her
present class A. 1
George Bailey

The Amount of Fee.....£ : : is received by me,

Committee Minute 24th Nov 1889

Character assigned A. 1