

ANNUAL SURVEYS.

No. _____ Survey held at Londou Date March 6th 1858
 on the Brig Jack Master Duke
 Tonnage 252 Built at Londou When built _____
 By whom built L. Snook Owners Peter Smith
 Port belonging to Londou Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat & Spouting Daylock

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of _____
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>1838</u>

Decks, Upper Deck Beams & Fastenings, Lower Deck Beams & Fastenings, Spirkettling, Plank Shears, Waterways, Hatchway Comings, Breasthooks, Transoms, Timbers of the Frame, Topsides, Wales, Plank and Treennails, Rudder, Windlass, Capstan, Pumps, Masts, Yards, &c., Sails, Cables, Anchors, Standing & Running Rigging, Copper.

Condition: Good (for Decks, Upper Deck Beams & Fastenings, Lower Deck Beams & Fastenings, Spirkettling, Plank Shears, Waterways, Hatchway Comings, Breasthooks, Transoms, Timbers of the Frame, Topsides, Wales, Plank and Treennails, Rudder, Windlass). Good (for Masts, Yards, &c., Sails, Cables, Anchors, Standing & Running Rigging, Copper).

General Observations and Opinion, as required by the Instructions,

At the present time the Copper has been repaired & the
 vessel overhauled aloft. She is in good & efficient order.

Committee Minute _____ 183

Character assigned _____

Lloyd's Register
 Foundation