

REPORT of SURVEY for REPAIRS.

6949
H

No. 301 Survey held at LONDON Date June 27 1859
 on the Ship Isaac Britton Master _____
 Tonnage 647 Built at LONDON When built 1835
 By whom built Green & Co Owners W. Wigram
 Port belonging to LONDON Destined Voyage India
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 1242, 3436 Dated 1837 Classed 12A1
 Port LONDON 4229, 6478,

Repairs *at the present time strutted, caulked from the keel up & sheathed with yellow metal to the top. & generally overhauled*
The whole appearance is very favourable

The Surveyor is also required to state the present Condition of the

Decks	<u>Good</u>	Transoms	<u>Good</u>	Windlass	
Upper Deck Beams & Fastenings	<u>4</u>	Timbers of the Frame	<u>4</u>	Capstan	
Lower Deck Beams & Fastenings	<u>4</u>	Topsides	<u>4</u>	Pumps	
Spirkettling	<u>4</u>	Wales	<u>4</u>	Masts, Yards, &c.	} <u>Good & efficient</u>
Plank Shears	<u>4</u>	Counter	<u>4</u>	Sails	
Waterways	<u>4</u>	Plank & Treennails (Outside to the Water's Edge)	<u>4</u>	Cables	
Hatchway Comings	<u>4</u>	Rudder	<u>Working & examined</u>	Anchors No. of	
Breasthooks	<u>1</u>	Copper	<u>Galt 1835</u>	Standing & Running Rigging	

General Observations and Opinion, as required by the Instructions,

In my opinion this ship is fully entitled to remain as at present classed 12A1
George Bayley

The Amount of Fee.....£ : : is received by me,

Committee Minute 27th Nov 1859

Character assigned Good & M

