

# ANNUAL SURVEYS.

6956

No. 746 Survey held at London Date Nov 6<sup>th</sup> 1840  
 on the Ship "Chelmsford" Master White  
 Tonnage 299 Built at London When built 1811  
 By whom built \_\_\_\_\_ Owners Chelmsford  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 Surveyed At in Dry Dock Imp<sup>l</sup>: Curling & Sons

Original Survey, No. 2038, Port of London

Classed \* A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>Not here</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Not here</u>	Masts, Yards, &c. _____
Spirkilling <u>"</u>	Top-sides _____	Sails <u>Good and</u>
Plank Shears <u>"</u>	Wales <u>in a good state</u>	Cables <u>sufficient</u>
Waterways <u>"</u>	Plank and Treennails (Outside to the Water's Edge) <u>Good</u>	Anchors No. of _____
Hatchway Comings <u>"</u>	Rudder <u>Good</u>	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper _____

General Observations and Opinion, At the present time repaired the Copper & Sails but  
 as required by the Instructions, the Ship is in very good condition and may  
remain as classed

Committee Minute 1<sup>st</sup> Dec 1840

Character assigned Not classed

No. 396 Survey held at London Date Nov 9<sup>th</sup> 1840  
 on the Ship Barge Ramco Master Belcher  
 Tonnage 505 Built at Greenock When built 1830  
 By whom built \_\_\_\_\_ Owners Anderson  
 Port belonging to Greenock Destined Voyage Calcutta  
 Surveyed At in Dry Dock Imp<sup>l</sup>: Newsons

Original Survey, No. 607 Port of Glyke, Ton 580

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>very good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>very good</u>	Timbers of the Frame <u>very good</u>	Masts, Yards, &c. _____
Spirkilling <u>very good</u>	Top-sides _____	Sails <u>good &amp;</u>
Plank Shears _____	Wales _____	Cables <u>sufficient</u>
Waterways _____	Plank and Treennails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>Nov 1840</u>

General Observations and Opinion, At the present time Shipped, launched and repaired  
 as required by the Instructions, the Bottoms, a very good faithful built Ship in  
excellent condition, and may remain as classed

Committee Minute 1<sup>st</sup> Dec 1840

Character assigned Not classed