

REPORT of SURVEY for REPAIRS.

No. 188 Survey held at London Date Nov 13th 1840 1840
 on the Ship Castle Lachlan Master Bruce
 Tonnage 435 Built at Glasgow When built 1811
 By whom built _____ Owners Gawson & Co.
 Port belonging to London Destined Voyage Samaran
 If Surveyed Afloat or in Dry Dock Carling Young & Co. Dock

Original Survey, No. 612, 1752, Dated Oct 1831, Classed *F. 1
3708, 4317, 4643, 5513, 5624, 6755, 6624.
 Port London

REPAIRS At the present time in consequence of damage
ships crushed from head of ship down - Rudder
refitted with all new Pinthes & Braces excepting one
Brace (midship) - Stern Post secured at the head, Trunks
refitted - 3 Strakes of Topside, & 2 Blackitake off 2 Cat Head Timbers
shifted on Lachlan and Down - (Timbers then very good)
added Rails & Timbers refitted & cutwater secured
as necessary - Bottom Felloes, Woodsheaths & Copper
to the sole and all the damages efficiently repaired

Present Condition of the

Decks	Transoms	Windlars
Upper Deck Beams & Fastenings	Timbers of the Frame	Capston
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water Edge)	Cables
Hatchway Comings	Rudder <u>1840</u>	Anchors No. of
Breasthooks	Copper <u>1840</u>	Standing & Running Rigging

General Observations and Opinion, In my opinion this ship is quite eligible
to remain as classed *F. 1

The Amount of Fee £ 2 : 0 : 0 is received by me, George Bayley

Committee's Minute 14 Dec 1840

Character assigned 1st class - sound