

REPORT of SURVEY for REPAIRS.

6966
171

No. 1047 Survey held at London Date April 3 1840
 on the Beck Australia Master Blanchard
 Tonnage 373 Built at Buckhurst When built 1826
 By whom built _____ Owners J. Nichol
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock London Dock

London 1967, 3153, 4588
 Original Survey, No. 3345, Dated Feb'y 1840 Classed A.1
 Port Liverpool

Repairs At the present time Copper stripped & bottom caulked from the keel up & encoppering. The old copper was quite smooth & free from wrinkles

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennils (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1840</u>	Standing & Running Rigging

General Observations and Opinion, as required by the Instructions, In my opinion this ship is eligible to remain as classed A.1
 © 2019 Lloyd's Register Foundation
 George Bayley

The Amount of Fee.....£ : : is received by me,
 Committee's Minute 1st Decr 1840
 Character assigned A.1