

REPORT of SURVEY for REPAIRS

6980

No. 572 Survey held at Londra Date May 11th 1840
 on the Ship John & Mary Master J. Cooper
 Tonnage 103 Built at Buffon When built 1834
 By whom built _____ Owners P. Cooper & Vidara
 Port belonging to Londra Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 104 Dated 1839 Classed 12 A 1

Port of Southampton Milford

Repairs All the present timbers caulked and coppered

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Sheers	Counter	Sails <u>Good</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables <u>Good</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinion, Appear in a very efficient state & capable to retain
 as required by the Instructions. in present shape

The Amount of Fee £ _____ is received by me,

Committee's Minute 1st Decr 1840

Character assigned 12 A 1