

REPORT of SURVEY for REPAIRS.

6989
[Handwritten initials]

Ceppering
 No. 314 Survey held at London Date April 20 1840
 on the Bayne Robert Master Teitler
 Tonnage 310 Built at Greenich When built 1814
 By whom built _____ Owners Seaver
 Port belonging to London Destined Voyage London to Mountserrat
 If Surveyed Afloat or in Dry Dock At the owners dock

Original Survey, No. 614, 2766, Dated _____ Classed Reat 24 6 5 1
 Port London 4496

Repairs at the present time - Stiffen, Caulk and
Recover the Stern - Caulk the Top-sides

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkutting	Wales <u>Good</u>	Masts, Yards, &c. <u>Good and Official</u>
Plank Shears <u>Good</u>	Counter	Sails
Waterways	Plank & Treennils (Outside to the Water's Edge)	Cables
Hatchway Comings	Kudler	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, The vessel is in good condition and may
remain as classed - & rather slack
 as required by the Instructions.



© 2019

The Amount of Fee £ _____ is received by me
 Committee's Minute 24 April 1840
 Character assigned Reat 24 6 5 1