

ANNUAL SURVEYS.

7006

No. 10 Survey held at Sidon Date Dec 20th 1840
 on the Swift Master Smith
 Tonnage 137 Built at Sunderland When built 1840
 By whom built _____ Owners Hull & Co
 Port belonging to Sunderland Destined Voyage Sunderland
 If Surveyed Afloat or in Dry Dock in the Sidon Dock

Original Survey, No. 1808 Port of LXXX Sunderland 1840 Classed A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails <u>Hull</u>
Plank Shears	Wales	Cables <u>Iron</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchor's No. of _____
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time sheath with yellow metal
 as required by the Instructions.

Committee Minute 14th Decr 1840

Character assigned

A 1

No. 10 Survey held at Sidon Date Dec 27th 1840
 on the By Master Mathews
 Tonnage 135 Built at Wrayport When built 1834
 By whom built _____ Owners Mathews
 Port belonging to _____ Destined Voyage St Lucia
 If Surveyed Afloat or in Dry Dock Sidon Dock

Original Survey, No. 4200 Port of Sidon 1834 Classed Continued A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails <u>Iron</u>
Plank Shears	Wales	Cables <u>Iron</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchor's No. of _____
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Longer condition to receive the present
 as required by the Instructions.

Committee Minute 14th Decr 1840

Character assigned

A 2

Lloyd's Register
Foundation