

ANNUAL SURVEYS. owners 7017 Hypocrite Change of

No. 200 Survey held at London Date 25th Nov 1840
 on the 1st March Master Henry
 Tonnage 1405 Built at New Brunswick When built 1831
 By whom built John B. B. Owners Reed
 Port belonging to John B. B. Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock Afloat & in Dry Dock by Mr. Clark

Original Survey, No. 611, 1447, Port of Liverpool London 700 Classified Fr. L
 The Surveyor is required to state the present Condition of the Top timbers & plating 16

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables <u>40 Short</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of <u>2 B. A. 1 Small Kedge</u>
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions, Her Store are incomplete notice left respecting them - Her Hull has been damaged from being on shore per Mr. Clark's report again also to be opened at Kedges, as necessary
 Committee Minute 14th Dec. 1840
 Character assigned Good at "hot open" for sea
Matthew Gibbs Sons London

No. 10 Survey held at London Date 16 Nov 1840
 on the Pore Master Royal
 Tonnage 308 Built at London When built 1833
 By whom built Thomson Owners Thomson
 Port belonging to London Destined Voyage London
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 623, 1447, Port of London Classified 10 A 1
 The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good</u>	Sails
Plank Shears	Wales	Cables <u>Suff. & good</u>
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions, Is in good and efficient condition and may be taken as a ship
 Committee Minute 14th Dec. 1840
 Character assigned 10 A 1
Matthew Gibbs Sons