

REPORT of SURVEY for REPAIRS.

7027

No. 930 Survey held at London Date Nov. 24 1840
 on the Rh. Musica Master Brilliant
 Tonnage 217 Built at Switzerland When built 1830
 By whom built _____ Owners Switzerland
 Port belonging to Switzerland Destined Voyage Switzerland
 If Surveyed Afloat or in Dry Dock Afloat in the Stags

Original Survey, No. 1072 Dated 1830 Classed 10 A 1
 Port of Switzerland

Repairs Bottom examined

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchor No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion Ship in a very efficient state in the hull & rigging
 as required by the Instructions, and well found in stores and appears likely to
retain her present value

The Amount of Fee.....£ 1 : 0 : 0 is received by me, Lloyd's Register
 Committee's Minute 11th Decr. 1840
 Character assigned 10 A 1