

ANNUAL SURVEYS.

7029

No. 503 Survey held at LONDON Date Dec 5th 1840
 on the Brig Pelissaria Master East
 Tonnage 146 Built at Yarmouth When built 1837
 By whom built _____ Owners R W Hyde
 Port belonging to LONDON Destined Voyage Barbadoes
 If Surveyed Afloat or in Dry Dock at Rotherhithe dock ways & dock

Original Survey, No. 132 Port of LONDON Sir R. B. 12th Classed A 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Breasthooks <u>good</u>	Capstan
Upper Deck Beams & Fastenings <u>good</u>	Transoms	Pumps
Lower Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good well seen</u>	Masts, Yards, &c.
Spirkettling _____	Topides <u>in good state</u>	Sails
Plank Shears _____	Wales _____	Cables <u>good and sufficient</u>
Waterways _____	Plank and Treenails _____ <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Coverings _____	Rudder _____	Standing & Running Rigging
	Windlass _____	Copper

LONDON 1/12/1840
Capitan's 1837 5 years

General Observations and Opinion, At the present time does not seem to be in the better state
 as required by the Instructions, the beam truss, all in a very good state; the vessel is in a
very good state throughout, and stands very firm. It is fit for the
safe conveyance of a very perishable cargo to any part of the
world and in my opinion should be classed * A 1

Committee Minute 11th Dec. 1840

Character assigned 3 A 1 Wm H. 1 Wm H. 1 Wm H. 1
Special 1-0 with the authority of

No. 372 Survey held at LONDON Date Dec 5th 1840
 on the Schooner Beacon Master Spive
 Tonnage 162 Built at Yarmouth When built 1837
 By whom built _____ Owners Simpsen
 Port belonging to LONDON Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock at Rotherhithe dock ways & dock

Original Survey, No. 1084, 1225 Port of LONDON Classed A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topides <u>good</u>	Sails
Plank Shears _____	Wales _____	Cables <u>good and sufficient</u>
Waterways _____	Plank and Treenails _____ <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Coverings _____	Rudder _____	Standing & Running Rigging
	Windlass _____	Copper

General Observations and Opinion, This vessel is in very a very excellent state
 as required by the Instructions, and in my opinion should remain a vessel
with the authority of

Committee Minute 11th Dec. 1840

Character assigned 11 A 1

© 2019
Lloyd's Register
Foundation