

ANNUAL SURVEYS.

7061

No. 150 Survey held at London Date Dec 1 1840
 on the B^t John Vale Master Coats
 Tonnage 276 Built at Chislehurst When built 1839
 By whom built _____ Owners Stall
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 814 Port of St. James July 1839 Classed GA1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Apper 1839 to 1840 - Apper good and
 as required by the Instructions, smooth & present time - in my opinion
she is eligible to be present class GA1

Committee Minute 15th Dec 1840

Character assigned GA1 Edward Apper

No. _____ Survey held at London Date Dec 2 1840
 on the B^t Maundy Master Morgan
 Tonnage 362 Built at Whitby When built _____
 By whom built 480 Owners Chapman & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. _____ Port of _____ Classed _____


The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Carried out to build & shipping to trade
 as required by the Instructions, on Dry Docks - she is in good condition
George Bayley

Committee Minute _____ 1840

Character assigned _____



Lloyd's Register
Foundation