

REPORT of SURVEY for REPAIRS.

No. 7063 Survey held at London Date June 28th 1837
 on the Schooner Swallow Master Arter
 Tonnage 116 Built at Gibraltar When built 1824
 By whom built _____ Owners Beffle & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mountain Dock

Original Survey, No. _____ Dated 1835 London

Port London

Repairs. *At the present time the remaining Iron Bolts
 have been secured, the Bottom stripped, thoroughly
 caulked & oakhauled. & recooped*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails
(Outside to the Water's Edge) _____
 Rudder _____
 Windlass _____
 Copstun _____

General Observations and Opinion,
 as required by the Instructions

*New Main shafts made, Rigging & Sails good efficient
 This vessel has passed her examination at this
 present time to be sound and in every good
 condition throughout. Her only opinion is
 eligible for the conveyance of her said freightable
 cargo but from all parts of her hold with safety &c.
 My opinion should be elapsed * N*

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183

Character assigned _____

Lloyd's Register Foundation