

REPORT of SURVEY for REPAIRS.

7114
A

No. 173 Survey held at Liver Date January 5th 1847
 on the By Diana Master S. F. Gillemea
 Tonnage 161 Built at Peterhead When built _____
 By whom built _____ Owners T. T. Jones
 Port belonging to Archangel Destined Voyage St. Wkes
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Dundee 310.
 Original Survey, No. 5211 Dated May 1840 Classified A. 1
 Port of Liver

REPAIRS In Feb. 1841 had new keel, Stowage, ^{new} upper course of the
after shafts of the bottom, & new ceiling below the old beams,
At the present time 4 pair of new rudders over to the floor
heads, bottom stipples caulked and sheathed with 1/2 inch
Iron over felt

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Siders	Counter	Sails <u>Good</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables <u>Efficient</u>
Hatchway Comings	Rudder	Anchor No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Seen every good condition throughout & is an efficient
hulk for the safe carriage of my & possible
cargoes and may continue so.

The Amount of Fee £ 1 is received by me, A. J. Gillemea

Committee's Minute 15th Jan'y 1847

Character assigned First class repair

© 2019

Lloyd's Register
Foundation