

ANNUAL SURVEYS.

7122

No. 14 Survey held at London Date Jan 2 of 184
 on the Ship Tamerlane Master M^r Kerrigan
 Tonnage 427 Built at Ux When built 1834
 By whom built _____ Owners Hewart & Co
 Port belonging to Genack Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Ship^r M^r Hibbins

Original Survey, No. 32 Port of Clyde, London 3794, 3886, Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Cupatan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, Sc.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, } *At the present time, Ship^r is, considered the bottom and old Sheathing (Bot^{om}) and Re-plastered on paper. The Ship is in good Condition and should remain*

Committee Minute 13th Jan^y 184/

Character assigned 10 A 1 *good* Wmth Clark

No. 506 Survey held at London Date Jan 3 of 184
 on the Bayne City of London Master Antiam
 Tonnage 230 Built at Leith When built 1837
 By whom built _____ Owners Jenkinson
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Ship^r Wain dock

Original Survey, No. 303 Port of Leith London 3344, 5572, Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Cupatan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, Sc.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, } *At the present time, Ship^r is, considered from the up over all to Waterway name, fitted & Pair of Stiple Stennons between deck & 3rd Pair under the Remains and 4th Pair of hanging knees to Water because the Ship is in a very good State and may remain as Classed*

Committee Minute 15th Jan^y 184/

Character assigned 12 A 1 *good* Wmth Clark

LON 609-0313