

REPORT of SURVEY for REPAIRS.

7131

No. 32 Survey held at London Date August 25 1837
 the Ship Duchess of Northumberland Master Roxburgh
 Tonnage 541 Built at Sunderland When built 1834
 By whom built Saug Owners Partin & Co
 Port belonging to London Destined Voyage Lyding?
 If Surveyed Afloat or in Dry Dock Blackwall Day Dock

Sunderland 72,
 Original Survey, No. 2110, 5392, Dated March 1836 Clasp'd 11A1
5425, 7049,
 Port London

Repairs. At the present time stopped, caulked from keel to top of
 hale & resheathed with yellow metal over 1/2 stakes of felt by
 the remainder tarred paper - Rudder & chum - ship being
 shod & seam caulked - generally overhauled

| | |
|--|---|
| The Surveyor to state the present Condition of | |
| Upper Deck Fastenings <u>Good</u> | Wales <u>Good</u> |
| Spirkettling <u>"</u> | Counter <u>"</u> |
| Plank Sheers <u>"</u> | Plank and Treeneals <u>"</u> <small>(Outside in the Water's Edge.)</small> |
| Top-sides <u>"</u> | Rudder <u>"</u> |
| Upper Deck with its Appendages <u>"</u> | Windlass <u>"</u> |
| Lower Deck Fastenings <u>"</u> | Captain <u>"</u> |

General Observations and Opinion, The appearance of this ship is favourable throughout
as required by the Instructions,
it is my opinion this vessel to remain as she
present Clasp'd 11A1
George Bayley

The Amount of Fee..... £ : : is received by me.

Committee Minute 10th 1837

Character assigned 11A1

Lloyd's Register
Foundation

REPORT OF SURVEY OF REPAIRS

2

T. P.
W. H. W. H. S. C.

Charles Graham Esq
Wright & Co
London



© 2019

Lloyd's Register
Foundation