

REPORT of SURVEY for REPAIRS.

No. 249 Survey held at London Date May 2 1887
 on the Shannon Richard Mount Master _____
 Tonnage 178 Built at Shrewsbury When built 1834
 By whom built W. G. Kelly Owners Walker
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock New Beam Dock

Original Survey, No. 1, Dated 1 1884 Capted 11.1
 Port Shrewsbury, London 5135,

Repairs. At the present time in consequence of having been
 when - several Pickets shifted. Caulked from keel
 to the Waterway beam & capped on Paper
 New Bowspike - Wing & Keel beam caulked

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treennails
 (Outside to the Water's Edge) _____
 Rudder _____
 Windlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

Parts Missing & in good condition
 This vessel general appearance is favorable - the
 as required by the Instructions, Clump & Keel on have the appearance of being
 Foreign Bales - The Store are some of them imperfectly
 repaired - It is my opinion the vessel is in good condition
 This is suitable to stand - George Bouley

The Amount of Fee..... £ : : is received by me

Committee Minute 10th June 1887

Character assigned 11th June 1887