

REPORT of SURVEY for REPAIRS.

1150

No. 302 Survey held at London Date January 2nd 1847
 on the Br Little Catherine Master _____
 Tonnage 404 Built at Bermuda When built _____
 By whom built _____ Owners Wanning & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in the London Dock
Change of Owners

Original Survey, No. 575, Dated May 1846 Classified A, 1 with the Certificate

Port of Sunderland, London 1810, 3607, Liverpool 3323, 3466,

REPAIRS

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Cepstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spir-ketting	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchor No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

Appears in a very efficient state for the safe conveyance of dry & perishable cargoes to & from all parts of the world and may retain her present class A, 1 with the Certificate

The Amount of Fee £ 1 is received by me, J. H. M. M. M.

Committee's Minute 22nd Jan'y 1847

Character assigned A, 1 with the Certificate

Lloyd's Register
Foundation