

ANNUAL SURVEYS.

No. 505 Survey held at London Date Feb. 2 1841
 on the Am City of Hamburgh Master Moore
 Tonnage 239 Built at London When built 1814
 By whom built _____ Owners Gen. Sir Navigation Co
 Port belonging to London Destined Voyage Hamburgh
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 1515, 3550 Port of London Classed 12 A 1
1815,

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Breasthooks <u>good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>good when seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. _____
Spirkettling <u>"</u>	Top-sides _____	Sails <u>good & sufficient</u>
Plank Shears <u>"</u>	Wales _____	Cables _____
Waterways <u>"</u>	Plank and Treennails <u>very good</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings <u>"</u>	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>new</u>

General Observations and Opinion,
 as required by the Instructions,

At the present time, Shipper can't see and
reappears the bottom in paper -
The vessel is in very good condition and may
remain as shipped

Committee Minute 12th Feb'y 1841

Character assigned 12 A 1 Good Cop

No. _____ Survey held at London Date Feb. 2nd 1841
 on the Ship Helara Master Slade
 Tonnage 728 Built at Calcutta When built 1815
 By whom built _____ Owners Slade
 Port belonging to London Destined Voyage Barbadoes
 If Surveyed Afloat in Dry Dock Mr. Pitchers

Original Survey, No. _____ Port of _____ Classed * A. 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms <u>Good when seen</u>	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Top-sides _____	Sails <u>Good & sufficient</u>
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>new</u>

General Observations and Opinion,
 as required by the Instructions,

The Ship is in very good Condition, and may
remain as shipped

Committee Minute _____ 1841

Character assigned _____

Lloyd's Register
 Foundation