

REPORT of SURVEY for REPAIRS.

No. 200 Survey held at London Date 3rd July 1841
 on the Robarts Master Eldon
 Tonnage 723 Built at Calcutta When built 1815
 By whom built _____ Owners Eldon
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry dock

Original Survey, No. 1689, 2772, Dated _____ Classed † M/1
3890, 4586, 5892, 7971

Port London
 REPAIRS 1841 Shipped bottom Coal then grise taken down and refitted generally overhauled and sheathed with yellow metal

Present Condition of the		
Decks _____	Transoms _____	Winlasses _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Capstan _____
Lower Deck Beams & Fastenings _____	Topsides _____	Pumps <u>good</u>
Spirkutting <u>good</u>	Wales <u>good</u>	Masts, Yards, &c. <u>New for m. see</u>
Plank Shears _____	Counter _____	Sails <u>2 Sails</u>
Waterways _____	Plank and Treenails (Outside to the Water's Edge) _____	Cables <u>Sufficient</u>
Hatchway Comings _____	Rudder _____	Anchors No. of _____
Breasthooks _____	Copper _____	Standing & Running Rigging <u>renewed</u>

General Observations and Opinion, It is in an efficient condition for the owner, or else of any and every other cargo, to and from all parts of the world and every Harbour as aforesaid

The Amount of Fee.....£ _____ is received by me,
 Committee's Minute 12th July 1841
 Character assigned Fit to receive cargo