

No. 310 Survey held at London Date March 16th 1841 7332
 on the By Governor Mr. Sean Master J. Morley
 Tonnage 252 Built at London When built 1833
 By whom built _____ Owners Finster & Co
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 5013, 5801 Port of London 1039 Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good* *Sufficient*

General Observations and Opinion, At the present time Masts & Upper works can't be
 as required by the Instructions, new Foremast & Rigging overhauled
Is in a very efficient state to continue on his present Voyage

Committee Minute 19th March 1841

Character assigned 12 A 1