

REPORT of SURVEY for REPAIRS.

No. 67 Survey held at LONDON Date 6th 2^d March 1841
 on the "M^r Hamus" Master Robson
 Tonnage 352 Built at Stockton When built 1787
 By whom built — Owners J. Marsham
 Port belonging to LONDON Destined Voyage India?
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1153 Dated — Classed F.1
 Port LONDON. Nive. 181, Lon. 3222, 5084, 6235.

REPAIRS

1841
 Two planks taken out of the wales Carbond side and two
 second hand planks put in, part new black stroke, after lengths
 of wales shifted, Starboard side part ~~new~~ black stroke, shifted
 with second hand plank, new pale bit, caulked from wales
 up, New fore hatch comings.

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In shifting the after ends of the wales 14 timbers —
 were exposed 9 were found very defective including the star counter
 timber some of them entirely decayed from the after part of the
 main channels forward 62 timbers were exposed 19 decayed. The
 upper deck comings are in good state, we are of opinion this ship

The Amount of Fee.....£ : : is received by me, is in a very unsafe condition

Committee's Minute 23rd March 1841

Character assigned Upper Character

Handwritten signatures and notes

is in a very unsafe condition
 and not entitled to her
 present class
 Continued
 Lloyd's Register
 Foundation
 L. 31 March to owner