

REPORT of SURVEY for REPAIRS.

No. 449 Survey held at London Date Feb. 10 & March 10 1841
 on the Barque "Princess Mary" Master Legg
 Tonnage 290 Built at Philadelphia When built 1838
 By whom built Legg Owners Legg
 Port belonging to London Destined Voyage Quebec
 If Surveyed Afloat or in Dry Dock Simultaneously afloat & afloat

Original Survey, No. 1268, 2349, Dated 4000, 4451, 5033, 6150, Classed F 1
 Port London

REPAIRS

At the present time, -
 Shifted 4 short planks in the keel abate &
 4 planks in the coupling. Caulked from the
 keel to waterways. Shipped 2 deck beams to knees.
 15 Ruffier stantions on the Starb. & 4 on the Larboard
 side. felled new Bulwarks & new stem butting
 outside.

Present Condition of the

| | | |
|-------------------------------|---|---------------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame } <u>not seen</u> | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales } <u>in a fair</u> | Masts, Yards, &c. } <u>good</u> |
| Plank Shears | Counter | Sails |
| Waterways | Plank & Treennails } <u>sound state</u> | Cables } <u>sufficient</u> |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion,

This ship is in a very fair state for the conveyance
 on any voyage of carrying cargo when their nature subject to wear
 damage, and in my opinion should remain as classed

The Amount of Fee £ 1 : - : - is received by me, Wm. Legg

Committee's Minute 2nd April 1841

Character assigned F 1 reassessed



© 2019

Lloyd's Register
Foundation

LON 60-0102