

REPORT of SURVEY for REPAIRS.

Change of Owners

739

No. 759 Survey held at London Date April 1st 1841
 on the By Mercury Master B Greenwell
 Tonnage 233 Built at Nova Scotia When built 1824
 By whom built _____ Owners R Brown
 Port belonging to Sunderland Destined Voyage Sunderland
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 19, 57, 79, Dated 1837 Classed A. A. expunged

Port of Waterford

REPAIRS

Caulked in 1840

At the present time a shake of the Ceiling above the turn of the Bidge taken up fore & aft, and found four timbers on the starboard side & five on the larboard side partly decayed all the remainder in a sound state -

Present Condition of the

Decks <u>Indifferent</u>	Transoms <u>Sound</u>	Windlass
Upper Deck Beams & Fastenings <u>Firm</u>	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings <u>1</u>	Topsides <u>Fair condition</u>	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails <u>g</u>
Waterways <u>Fair condition</u>	Plank and Treennails (Outside to the Water's Edge)	Cables <u>Efficient</u>
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Over</u>	Standing & Running Rigging

General Observations and Opinion

This vessel is throughout in good condition for the safe conveyance of cargoes not in their nature subject to sea damage and should be classed E. 1


W. H. H. H.

The Amount of Fee.....£ 1 : - : - is received by me, *J. H.*

Committee's Minute 2nd April 1841

Character assigned E. 1 55246 1841

J. H.



© 2019

Lloyd's Register Foundation
LON 610-0109