

REPORT of SURVEY for REPAIRS.

Change of owners for 7406

No. 282 Survey held at London Date 5th April 1842
 on the My Fox Master Regent J. Rogers
 Tonnage 110 Built at Berwick When built 1805
 By whom built _____ Owners See
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 5720 Dated _____ Classed F.L.
 Port London

REPAIRS

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails <u>None on board</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables <u>two chains, one lead no Hauling</u>
Hatchway Comings	Rudder	Anchors No. of <u>2 B 1 Kedge</u>
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, The bottom is good, the Wales Black Strakes and topsides (excepting a few planks recently shifted) is in a bad condition the Decks are also bad for want of the beams knees &c is in old and much worn condition the keel throughout is in an inefficient state fit only for the conveyance
 The Amount of Fee.....£ 10 : 0 : 0 is received by me, officers not liable to sea damage on short notice

Committee's Minute 6th April 1844
 Character assigned Reduced to F

[Signature]

[Signature]

Notice Voyages and should be to Reg. Office
25th April
Stores not on board
 Lloyd's Register Foundation

111019107