

REPORT of SURVEY for REPAIRS.

No. 180 Survey held at London Date April 14 & 15 & 19 1841
 on the Bj Elbe Master Robson
 Tonnage 211 Built at Sunderland When built 1826
 By whom built _____ Owners Robson
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Hackwoods Ways

Original Survey, No. 369, 2686, Dated May 1840 Classed * AE 1
4019, 5300, 6432.
 Port London

REPAIRS

at the present time shifted a good part of
 the Planksheers, caulked from copper up and
 generally overhauled — and
 eighteen feet of Shear stake on the Starboard side
 Twenty two feet of ditto on the Starboard side
 six new stations & one new Plank on the Topside

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Smooth & Good</u>	Standing & Running Rigging

General Observations and Opinion,

In my opinion this vessel is eligible to
 remain as classed AE 1

George Bayley

The Amount of Fee £ 1 : 0 : 0 is received by me, *Robson*

Committee's Minute 23rd April 1841

Character assigned AE 1 passed repairs
Plank

Special L2. 2. 0 damage



© 2019

Lloyd's Register
 Foundation

LON 610-0171