

ANNUAL SURVEYS.

7495
1841

No. 82 Survey held at London Date April 26 1841
on the Ship Mandarin Master _____
Tonnage 425 Built at Hyllon When built 1834
By whom built Gales Owners J B Gason?
Port belonging to Greenock Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 1768, 2274 Port of Liverpool 1838 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treencils (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

*Caulked aloft and painted copper - in
my opinion the ship is fit to be
classified 10 A 1*

Committee Minute 14th May 1841

Character assigned

10 A 1

[Signature]

[Signature]

No. 80 Survey held at London Date April 26 1841
on the Ship Malcolm Master Ball
Tonnage 605 Built at London When built 1826
By whom built _____ Owners Ephraim
Port belonging to London Destined Voyage India
If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 1049, 3762 Port of London April 1840 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treencils (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
as required by the Instructions,

*At the present time caulked well and I find
the planks in becoming defecting around
the bolts in the topsides - at present they are
made secure for a time - Under these circumstances*

Committee Minute 14th May 1841

Character assigned

10 A 1

*I think that the ship can scarcely
be deemed fit to be classified 10 A 1
Clap -*