

ANNUAL SURVEYS.

7523

No. 1187 Survey held at London Date 11 May 184/1
 on the Ch^r Lavinia Master Mara
 Tonnage 151 Built at Lynn When built 1825
 By whom built - Owners Royce & Prior
 Port belonging to London Destined Voyage Alicant
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1187 Port of London Li. 3668 Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Breasthooks <u>-</u>	Capstan <u>-</u>
Upper Deck Beams & Fastenings <u>-</u>	Transoms <u>-</u>	Pumps <u>-</u>
Lower Deck Beams & Fastenings <u>-</u>	Timbers of the Frame <u>-</u>	Masts, Yards, &c. <u>-</u>
Spirkettling <u>-</u>	Topsides <u>-</u>	Sails <u>Sufficient</u>
Plank Shears <u>good</u>	Wales <u>good</u>	Cables <u>and good</u>
Waterways <u>-</u>	Plank and Treenails (Outside to the Water's Edge.) <u>-</u>	Anchors No. of <u>-</u>
Hatchway Comings <u>-</u>	Rudder <u>-</u>	Standing & Running Rigging <u>-</u>
	Windlass <u>-</u>	Copper <u>-</u>

General Observations and Opinion,
 as required by the Instructions,

Strike of Deck next the waterway shifter has
curved inwards and cannot be seen fully - every
visible part appears in good and efficient condition for
 Committee Minute 11th May 184/1
 Character assigned A. 1
The possibility of any repairs having
been made to the waterway shifter
may be ascertained by the
Surveyor

No. - Survey held at - Date - 184/-
 on the - Master -
 Tonnage - Built at - When built -
 By whom built - Owners -
 Port belonging to - Destined Voyage -
 If Surveyed Afloat or in Dry Dock -

Original Survey, No. - Port of - Classed -

The Surveyor is required to state the present Condition of the

Decks <u>-</u>	Breasthooks <u>-</u>	Capstan <u>-</u>
Upper Deck Beams & Fastenings <u>-</u>	Transoms <u>-</u>	Pumps <u>-</u>
Lower Deck Beams & Fastenings <u>-</u>	Timbers of the Frame <u>-</u>	Masts, Yards, &c. <u>-</u>
Spirkettling <u>-</u>	Topsides <u>-</u>	Sails <u>-</u>
Plank Shears <u>-</u>	Wales <u>-</u>	Cables <u>-</u>
Waterways <u>-</u>	Plank and Treenails (Outside to the Water's Edge.) <u>-</u>	Anchors No. of <u>-</u>
Hatchway Comings <u>-</u>	Rudder <u>-</u>	Standing & Running Rigging <u>-</u>
	Windlass <u>-</u>	Copper <u>-</u>

General Observations and Opinion,
 as required by the Instructions,

Committee Minute - 184/-

Character assigned -



© 2019

Lloyd's Register
 Foundation