

# ANNUAL SURVEYS.

7530

No. 25 Survey held at London Date May 10<sup>th</sup> 1841  
 on the By Ocean Master Patterson  
 Tonnage 100 Built at Berwick When built 1037  
 By whom built \_\_\_\_\_ Owners Patterson  
 Port belonging to Berwick Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock on the Mays

Original Survey, No. 5500 Port of London 1039 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>in</u> <u>1030</u>

General Observations and Opinion, Bottom examined & Copper patched  
 as required by the Instructions, Is in a very efficient state to retain her  
present shape

Committee Minute 14<sup>th</sup> May 1841  
 Character assigned 11A1

No. 92 Survey held at London Date May 10<sup>th</sup> 1841  
 on the Bk Jane Master Warren  
 Tonnage 304 Built at New Brunswick When built 1039  
 By whom built \_\_\_\_\_ Owners R Duke  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock St Katharine's Dock

Original Survey, No. 5069 Port of London 1040 Classed 4A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Is very firm at her fastenings, and appears in an  
 as required by the Instructions, efficient state to continue her present shape

Committee Minute 14<sup>th</sup> May 1841  
 Character assigned 4A1