

REPORT of SURVEY for REPAIRS.

& Change of Owners

1546

No. 444 Survey held at London Date May 18th 1841
 on the Ship John McTearan Master D Mc Donald
 Tonnage 500 Built at Quebec When built 1833
 By whom built _____ Owners Phillipps & Tripleday
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock London Dock

Clyde 364,
 Original Survey, No. 6002 Dated January 1840 Classed A, 1 S, 3 ¹⁸⁴⁰ years
 Port London

REPAIRS At the present time at the recommendation of Mr Bayley
Waterways rubbed & the plank next the Waterway shifted
& partially caulked

Has been in the Dry Dock & bottom examined
also surveyed by Mr Bayley & Mr Clark

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass _____
Upper Deck Beams & Fastenings <u>Good & Firm</u>	Timbers of the Frame _____	Capstan _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps _____
Spirkettling _____	Wales <u>"</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears _____	Counter <u>"</u>	Sails <u>"</u>
Waterways <u>Good</u>	Plank & Treennails <u>Good</u> (Outside to the Water's Edge)	Cables <u>Efficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Anchors No. of _____
Breasthooks <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>part new</u>

General Observations and Opinion

Is firm at her fastenings & from her appearance
I am of opinion she may continue as before

The Amount of Fee.....£ 3 : : is received by me, W. R. Clark

Committee's Minute 21st May 1841

Character assigned A, 1 used repairs



© 2019

Lloyd's Register
 Foundation
 LON G10-0263