

ANNUAL SURVEYS.

7565

No. 300 Survey held at London Date May 12th 1841
 on the Barque Lord Godwin Master May
 Tonnage 361 Built at Hull When built 1828
 By whom built _____ Owners Godwin & Lee
 Port belonging to London Destined Voyage _____
 Surveyed ~~Afloat~~ in Dry Dock Sedgwick dock

Original Survey, No. 705, 1507, Port of London Classed *A1
2242, 3530, 5369, 5373, Portsmouth 1441

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms <u>not seen</u>	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>good &</u>
Plank Shears	Wales <u>"</u>	Cables <u>sufficient</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging
	Windlass <u>"</u>	Copper <u>New 1841</u>

General Observations and Opinion, At the present time. Shipped, Caulked from keel to
 as required by the Instructions, waterways; felted (with Bonaidades felt) & coppered the Bottom
The ship is in a good & efficient state, & in my opinion should
remain as classed

Committee Minute 25th May 1841
 Character assigned 1st Anterior Wm. J. Clark

No. 165 Survey held at London Date May 12th 1841
 on the Brig "Africanus" Master Sammoner
 Tonnage 485 Built at Yarmouth When built 1838
 By whom built _____ Owners Forster & Smith
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock For & aft ways

Original Survey, No. _____ Port of _____ Classed 12 A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good &</u>
Plank Shears	Wales	Cables <u>sufficient</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, This vessel is in very good condition & in my
 as required by the Instructions, opinion should remain as classed

Committee Minute _____ 184
 Character assigned _____ Wm. J. Clark



© 2019

Lloyd's Register
Foundation

LON 610-0284