

ANNUAL SURVEYS.

75/1

No. ²⁴⁷ Survey held at London Date 24 May 1841
 on the Richard Brown Master Dunlop
 Tonnage 252 Built at Glasgow When built 1826
 By whom built _____ Owners Campbell
 Port belonging to Glasgow Destined Voyage Glasgow?
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 143 Port of Clyde, Lon 240, Cly 141, Lon. 5316, Cly. 770. Classed 1A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>Good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails <u>Sufficient</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>Good</u>
Waterways <u>Good</u>	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion,

as required by the Instructions,

Several of the Hold Beam knees are partially broken others split I suggested that iron hanging knees be put in or otherwise a shelf wrought under the beams which the Master promises to do when they arrive at Glasgow
Superintendent

Committee Minute 25th May 1841

Character assigned _____

No. ²³⁷ Survey held at London Date 24 May 1841
 on the Catherine Elizabeth Master Merritt
 Tonnage 304 Built at London When built 1833
 By whom built Saunders Owners Frazer & Co
 Port belonging to London Destined Voyage Greenwich
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 971, 2703 Port of London Classed 1A1
3870, 4375, 6377, 6934,

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Sufficient</u>
Plank Shears _____	Wales _____	Cables <u>Good</u>
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion,

as required by the Instructions,

Is in the most efficient condition and may be continued as classed
Superintendent

Committee Minute 25th May 1841

Character assigned 1A1



© 2019

Lloyd's Register Foundation

101610-0290