

REPORT of SURVEY for REPAIRS.

No. 7603 Survey held at London Date May 16 1845
 on the Ship Wellington Master Liddle
 Tonnage 473 Built at Bombay When built 1810 94
 By whom built _____ Owners Crown
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 2673, 3423 Dated _____ Classed *A
 Port London 4243, 5371,

Repairs

At the present time, stripped off the
 Copper and sheathed with yellow Metal
 on the old ^{wood} sheathing. Caulked the Wals,
 Topsides, &c.

Left wood with the carpenter on the 14th inst. to let
 the Captain. The sheathing must come off on coming
 to the Office in the afternoon found there was an exception
 to Rule for Trade Ships, on calling in the yard this
 morning found the ship sheathed with yellow Metal

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

This ship is in very good condition afloat
 the sheathing has been on the bottom 8 years
 & according to the Rule should be stripped, or
 a specimen survey called to examine the caulking
 which has not been complied with. At the 14th inst.

The Amount of Fee £ _____ is received by me,

Committee's Minute 19th May 1845

Character assigned Deferring Write to Surveyor