

REPORT of SURVEY for REPAIRS.

Damage

7029

Survey held at London Date May 28 1841
 Barque "Cape Packets" Master Lamb
 Age 2349 Built at Sunderland When built 1838
 Whom built _____ Owners Lamb
 belonging to London Destined Voyage Cape
 surveyed at in Dry Dock Eastward's dock

Original Survey, No. 1039 Dated _____ Classed 12 A 1

at Sunderland, London 5870.

REPAIRS

At the present time

Stripped off the Copper, caulked the bottom and Re-plated; sheathed with yellow Metal.

Present Condition of the

Decks <u>Good</u>	Transoms _____	Windlass _____
Upper Deck Beams & Fastenings <u>✓</u>	Timbers of the Frame <u>not seen</u>	Capstan _____
Lower Deck Beams & Fastenings <u>✓</u>	Topsides <u>Good</u>	Pumps _____
Spirketting <u>✓</u>	Wales <u>✓</u>	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>✓</u>	Counter <u>✓</u>	Sails <u>sufficient</u>
Waterways <u>✓</u>	Plank & Treenails (Outside to the Water's Edge) <u>✓</u>	Cables _____
Hatchway Comings <u>✓</u>	Rudder <u>✓</u>	Anchors No. of _____
Breasthooks _____	Copper <u>Yellow Metal</u>	Standing & Running Rigging _____

General Observations and Opinion.

This Ship is in a good and efficient state fit for the safe conveyance of dry & perishable goods to & from all parts of the world and in our Opinion should remain as Classed.

The Amount of Fee.....£ : : is received by me. Wm. J. Clark

Committee's Minute 15th June 1841

Character assigned 12 A 1 used Me
LR



Lloyd's Register Foundation
 LON 610-0356