

ANNUAL SURVEYS.

7638

No. 478 Survey held at London Date June 9th 1841
 on the Ship Bombay Master Furley
 Tonnage 1280 Built at Bombay When built 1809
 By whom built _____ Owners Pirie & Co.
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock East India docks

Original Survey, No. 35,5036, Port of London 5047, 6411, Classed *A
 The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Sent a note to the Owners June 9th calling attention
 as required by the Instructions, to the state of the Schober & Spirkettling, some part of
which is defective round the fastenings;
The Caulking in the upper works is very slack in the bulk
& scuppers; the ship in my opinion wants a general overhaul
 Committee Minute 18th June 1841
2nd July in the upper works
 Character assigned 4th class rather slack Owner
W. H. Shaw

No. Supp Survey held at London Date June 1841
 on the Ship Maria Somes Master _____
 Tonnage 100 Built at Warrmouth When built 1841
 By whom built _____ Owners Somes
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Messrs. Curling & Youngs

Original Survey, No. 454 Port of Warrmouth Classed 12A
 The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>all Teak</u>
Spirkettling	Topsides	Sails <u>2 sails</u>
Plank Shears	Wales	Cables <u>240 fms 180 fms & 240 fms</u>
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of <u>3 B 18 1/2 1/2 1/2</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>YM 11</u>

General Observations and Opinion, at the present time Caulked & sheathed the
 as required by the Instructions, Bottom with yellow metal; a very good, substantial
and faithful built ship, well deserving
her character
 Committee Minute 18th June 1841
 Character assigned 12A