

7706
HLL

REPORT of SURVEY for REPAIRS.

& Continuation & Change of Owners

No. 422 Survey held at London Date July 16th 1847
on the Bk Guiana Master Bauman
Tonnage 256 Built at Sunderland When built 1834
By whom built _____ Owners J Duff
Port belonging to Port Adelaide Destined Voyage Port Adelaide
If Surveyed Afloat or in Dry Dock Ratcliffe Pross Dock

Original Survey, No. 1090, 3418, Dated 1837 Classed 9 A.1
Port London expunged

REPAIRS At the present time sheathing renailed, caulked from the sheathing to the gunwale and throat bolts of the iron hanging knees renewed, several bolts & keennails driven out for examination & found in good condition, ~~and~~ the Waterways, Beams, Hawse timbers, Hought-head Breasthooks, Transoms, Floors, Keelsons, Planking outside & inside, the Frame and inner surface of the outside planking when seen, Decks & Comings are all in a sound and efficient state and the Shear & general form appear in its original shape

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Well</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper <u>July 1848</u>	Standing & Running Rigging

General Observations and Opinion, Is throughout in a very efficient state, no appearance of weakness or decay and we are of opinion she may be continued
At for as many years as the rule will permit say three
years from 1840

The Amount of Fee £ 3 : - is received by me, W. M. M. M. M.
Committee's Minute 16th July 1847
Character assigned Class 3 A 1 from 1840 George Bayley