

REPORT of SURVEY for REPAIRS.

No. 7713 Survey held at London Date Sept 26 to July 6th 1841
 on the 137 Dawson Master Price
 Tonnage 227 Built at Whitehaven When built 1826
 By whom built _____ Owners _____
 Port belonging to Lancaster Destined Voyage Lancaster
 If Surveyed Afloat or in Dry Dock Kings Dock

Original Survey, No. _____ Dated 1838 Classed X. A. 1

Port London

REPAIRS at the present time strakes - 5th & 6th strakes put to hold beams
2 lower strakes of keel & strakes laid Quarter & 4 to Starboard
Quarter shifted being rinned - new gripe - being caulked
from the keel up to all the lower deck fastenings bolts
shifted & recopied as before

The timber of the frame very good & sound when opened

Present Condition of the

Decks <u>Good</u>	Transoms <u>Good fully exposed</u>	Windlass _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Capstan _____
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>"</u>	Pumps _____
Spirkettling <u>Good</u>	Wales <u>2 new strakes</u>	Masts, Yards, &c. <u>Good by</u>
Plank Shears <u>"</u>	Counter <u>Good</u>	Sails <u>efficient</u>
Waterways <u>"</u>	Plank & Treennails (Outside to the Water's Edge) <u>4</u>	Cables _____
Hatchway Comings <u>"</u>	Rudder <u>4</u>	Anchors No. of _____
Breasthooks <u>"</u>	Copper <u>1841</u>	Standing & Running Rigging _____

General Observations and Opinion, This vessel is now in a good and efficient condition
for remaining as at present classed X. A. 1

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____

Special Repair to 2.2



© 2019

Lloyd's Register
Foundation

LON 610-0447