

REPORT of SURVEY for REPAIRS.

No. 649 Survey held at London Date July 20th 1844
 on the Bk. Imeline Master J. Hudson
 Tonnage 294 Built at Alco. Corkin When built 1835
 By whom built _____ Owners C. Mutton
 Port belonging to London Destined Voyage Salipax
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 222 Dated _____

Classed A, 1

Port London

4071, 5895

REPAIRS

At the present time Water & Upperworks caulked and a stroke of the Ceiling above the turn of the Bidge on both sides from Stem to the Mainmast and found all the timbers in a sound & good condition

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>None</u>
Plank Shears	Counter	Sails <u>Good</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchor No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion

From the general good condition of the fastenings of the planking outside & inside I am of opinion she may continue in her present shape

The Amount of Fee.....£ _____ is received by me,

Committee's Minute 30th July 1844

Character assigned H.M. S.S. 4

Lloyd's Register
Foundation