

ANNUAL SURVEYS.

7827

No. ¹²⁹ Survey held at London Date August 16 1841
 on the Mer Gorge Returns Master _____
 Tonnage 334 Built at Notant Town When built 1839
 By whom built _____ Owners John H
 Port belonging to Notant Town Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Shed Dock

Original Survey, No. 5130 Port of South Sept 1839 Classed A1

The Surveyor is required to state the present Condition of the

Decks <u>Lighter & Sound</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>3</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>3</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treennails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge.)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, The last wood in the Deck appears to be much
 as required by the Instructions, affected by drought or moisture and does not
seem to be suitable for those parts subject to such
exposure as the Deck - There does not appear to any
decay or giving way in any part of
the fastenings - I think that the should
remain as elapsed - George Bayley

Committee Minute 16 August 1841

Character assigned To remain as is
is in the Dock and as is
or repaired

No. ¹²⁹ Survey held at London Date August 17 1841
 on the Atterial Moor-drum Master Good
 Tonnage 392 Built at Whitby When built 1827
 By whom built _____ Owners Scott & Paul & Co
 Port belonging to London Destined Voyage Guiana
 If Surveyed Afloat or in Dry Dock Shed Dock

Original Survey, No. 330,374 Port of London Restored 1839 ¹⁴⁵ Classed A1
129, 133, 1, 5103,

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling _____	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treennails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge.)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, After examination and repairs when
 as required by the Instructions, acquired an opinion that she is eligible to
remain as elapsed A1
George Bayley

Committee Minute 20th August 1841

Character assigned Restored