

# REPORT of SURVEY for REPAIRS.

7856  
AD

No. 592 Survey held at London Date July 12 to 19<sup>th</sup> 1841  
 on the Ship Lord Auckland Master W. Donald  
 Tonnage 480 Built at Calcutta When built 1836  
 By whom built 828 Owners Brown  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 Surveyed ~~at~~ in Dry Dock Blackwall yard

Original Survey, No. 592 Dated \_\_\_\_\_ Classed 12 A1

Port London

REPAIRS At the present time fitted a new Head Stow, Rub  
 berthug & new listings and caulked the boards ends.  
 Pales & topside & the fore channels. Fitted a new  
 false back 2 feet 6 inches at the head of the beam - replaced  
 the Bottom.

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, This is a strong built Ship; is in a very efficient  
 State for the safe conveyance of the & perishable goods to &  
 from all parts of the world, and in an opinion should  
 remain as classed.

The Amount of Fee £ 3 : - is received by me, W. Donald

Committee's Minute 24th August 1841

Character assigned 12 A1 Lord Auckland

© 2019  
 Lloyd's Register  
 Foundation