

# ANNUAL SURVEYS.

7874

No. 30 Survey held at London Date August 20<sup>th</sup> 184 1  
 on the Schooner "Pami" Master Tharson  
 Tonnage 134 Built at Reidport When built 1814  
 By whom built \_\_\_\_\_ Owners London Steamship Shipping Ass<sup>n</sup>  
 Port belonging to London Destined Voyage Waterford  
 If Surveyed Afloat or in Dry Dock London dock

Original Survey, No. 30, 2561 Port of London

Classed \* A. 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>good</u>	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>in a</u>	Timbers of the Frame <u>good when run</u>	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides	Sails <u>good</u>
Plank Shears <u>in a</u>	Wales	Cables <u>efficient</u>
Waterways	Plank and Treennails <u>good</u>	Anchors No. of
Hatchway Comings	(Outside to the Water's Edge.) Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time condition the bottom  
 as required by the Instructions, The vessel is in a very good sound state and  
in my opinion should remain a classed

Committee Minute 3rd Septe 184 1

Character assigned A. 1 Antivist Wm. J. Clark

No. 31 Survey held at London Date August 4<sup>th</sup> 184 1  
 on the Barque "Alfred" Master Shunt  
 Tonnage 176 Built at Chittagong When built 1818  
 By whom built \_\_\_\_\_ Owners Shunt & Co.  
 Port belonging to London Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock London dock

Original Survey, No. 31, 2562 Port of London

Classed \* A. 1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails <u>in a</u>	Anchors No. of
Hatchway Comings	(Outside to the Water's Edge.) Rudder	Standing & Running Rigging
	Windlass	Copper <u>1841</u>

General Observations and Opinion, Ship's hull painted and sheathed with yellow  
 as required by the Instructions, metal at the present time.

The ship appears in very good condition and in my  
opinion should remain a classed

Committee Minute 3rd Septe 184 1

Character assigned A. 1 Watermark Record Wm. J. Clark