

# ANNUAL SURVEYS.

7880

No. 123 Survey held at London Date August 31 1841  
 on the Bk Admiral Murray Master Richardson  
 Tonnage 392 Built at Whiteby When built 1827  
 By whom built      Owners Half 1/2  
 Port belonging to London Destined Voyage Dumekran  
 If Surveyed Afloat or in Dry Dock Not India Dock

Original Survey, No. 339, 37 1/4 Port of London  
4200, 4331, 5163, 7827.

1839 Classed 10 AN Return 6 A

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good &amp; Sec</u>	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound &amp; secure</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well stowed</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Is thought to be in a very efficient state and  
 as required by the Instructions, appears in every respect eligible to retain her  
present flag

Committee Minute 7th Septe 1841

Character assigned Not 30 6 A

No. 448 Survey held at London Date August 31 1841  
 on the Bk British Minarch Master Bayley  
 Tonnage 310 Built at Newcastle When built 1825  
 By whom built      Owners Graham  
 Port belonging to London Destined Voyage       
 If Surveyed Afloat or in Dry Dock Not India Dock

Original Survey, No. 961, 1033 Port of London  
5441, 6113, 7023,

1840 Classed 10 AN Return 1 A

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound &amp; secure</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Has no appearance of weakness or decay and is  
 as required by the Instructions, altogether in a very good state of efficiency  
to retain her present flag

Committee Minute 7th Septe 1841

Character assigned Not 40 7 A