

ANNUAL SURVEYS.

7880

No. 123 Survey held at London Date August 31 1841
 on the Blk Admiral Murray Master Richardson
 Tonnage 392 Built at Whiteby When built 1827
 By whom built Owners Self
 Port belonging to London Destined Voyage Danish
 If Surveyed Afloat or in Dry Dock Not India Dock

Original Survey, No. 339, 37 1/4 Port of London
4200, 4331, 5163, 7827.

1839 Classed Return 6 A

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Is in a very efficient state and
 as required by the Instructions, appears in every respect eligible to retain her
present flag

Committee Minute 7th Septe 1841

Character assigned Not 30 6 A

No. 448 Survey held at London Date August 31 1841
 on the Blk British Minarch Master Bayley
 Tonnage 310 Built at Newcastle When built 1825
 By whom built Owners Green
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock Not India Dock

Original Survey, No. 961, 1033 Port of London
5441, 6113, 7023,

1840 Classed Return 1 A

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treennails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, Appears appearance of workmanship on board and is
 as required by the Instructions, altogether in a very good state of efficiency
to retain her present flag

Committee Minute 7th Septe 1841

Character assigned Not 40 7 A