

ANNUAL SURVEYS.

189

No. 70 Survey held at London Date Sept. 7th 184 1
 on the Schwenck General Ward Master G. Ware
 Tonnage 172 Built at Canes When built 1806
 By whom built _____ Owners Robert
 Port belonging to London Destined Voyage Madagascar
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 68, 4275, 6588, 7405 Port of London April 184 1 Classed *E1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treennails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

Good *Good* *Good & Efficient* *New 1841*

General Observations and Opinion, Has now had new Lumen Rigging - She is in
 as required by the Instructions, a good & efficient state and fully eligible to remain
as classed *E1

Committee Minute 10th Sept 184 1

Character assigned B.1 Asterisk

George Bayley

No. _____ Survey held at _____ Date _____ 184 _____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treennails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

General Observations and Opinion,
 as required by the Instructions,

Committee Minute _____ 184 _____

Character assigned _____



© 2019

Lloyd's Register
 Foundation