

# ANNUAL SURVEYS.

1915

No. 1011 Survey held at London Date August 14th 1841  
 on the Ship Capard Master Rae  
 Tonnage 408 Built at Whitby When built 1811  
 By whom built \_\_\_\_\_ Owners Crawford  
 Port belonging to Newcastle Destined Voyage Mixed  
 If Surveyed Afloat or in Dry Dock Douglas Dock

Original Survey, No. 621 Port of Liverpool Nov. 30, Dec. 14/77, Nul. 311. Dec. 26, 6153, 7342. Classed A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings <u>Good</u>	Transoms	Pumps
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Tweenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, This Ship is very much out of condition her Main Keelson as required by the Instructions, is decayed and the Ship has not been efficiently repaired. Notice instructing was duly given to enter into repairs when the ship first docked - but the owner declines doing anything efficient and the circumstances seem of opinion that she should be marked "Wants Repair".

Committee Minute 17th Sept. 1841  
 Character assigned Exchange Character  
Wants Repair  
John to trans George Bayley  
R. Williams

No. 87 Survey held at London Date Sept 7 1841  
 on the Ship David Lyon Master Selby  
 Tonnage 476 Built at Spurwich When built 1819  
 By whom built S. Bayley Owners Selby  
 Port belonging to London Destined Voyage Jamaica  
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 1115, 3705 Port of Liverpool 4389, 5573, 6070, Classed A.1  
Returned 7 years 1834

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topides <u>Good</u>	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Tweenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Good</u>

General Observations and Opinion, The Ship appears to be throughout in good condition and eligible to remain as classed A.1

Committee Minute 17th Sept. 1841  
 Character assigned Post 7 to  
George Bayley