

ANNUAL SURVEYS.

1916

No. 377 Survey held at London Date Sept 14 184/7
 on the B^t Charles Master Dallin
 Tonnage 231 Built at Witley When built 1805
 By whom built _____ Owners Langlas - Port St. Anne
 Port belonging to London Destined Voyage Tobago
 If Surveyed Afloat or in Dry Dock Duke Street Dock

Original Survey, No. 1227, 2466 Port of London May 1840 Classed F.1
 The Surveyor is required to state the present Condition of the
3708, 5202, 5780, 6423, 6933, 7025.

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Sept 1841</u>

General Observations and Opinion, Condition Waterway Beam & Rep. Copper - She
 as required by the Instructions, appears fully eligible to remain as classed F.1

Committee Minute 17th Sept 184/7

Character assigned B.1

George Bayley

No. 146 Survey held at London Date Sept 14 184/7
 on the Ship Caroline Master Campbell
 Tonnage 473 Built at Swanwick When built 1800
 By whom built George Bayley Owners Malcolm
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Guarling Dock

Original Survey, No. 2466, 5343 Port of London Aug 1840 Classed F.1
5372, 6730

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Sept 1841</u>

General Observations and Opinion, Four Lower Deck Beams & One Half Beam
 as required by the Instructions, split together with several knees - The frame exposed
in good fair condition - May be said to remain as classed F.1

Committee Minute 17th Sept 184/7

Character assigned B.1

George Bayley

Sept 15. 1841
3 Repairs
& Amendments
11



© 2019

Lloyd's Register
Foundation