

REPORT of SURVEY for REPAIRS.

& Change of Owners

1931
J.P.K.

No. 57 Survey held at London Date July 26th 1841
 on the Bk Canada Master E. J. ...
 Tonnage 264 Built at Maryport When built 1839
 By whom built _____ Owners John ... Harrett
 Port belonging to London Destined Voyage West Indies Robert Town
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 93 Dated 1839 Classed 12 A 1


Port of Maryport

REPAIRS

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Copstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails
Waterways	Plank and Treenails <small>(Outside to the Water's Edge)</small>	Cables <u>Sufficient</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, The ship is in a very efficient state to continue in her present class



© 2019 *J.P.K.*

The Amount of Fee £ 1 : - : - is received by me, *J.P.K.*

Committee's Minute 25th Sept 1841

Character assigned 12 A 1

Lloyd's Register
Foundation