

ANNUAL SURVEYS.

1919

No. 352 Survey held at London Date Sept 10 1841
 on the Barque Amy Tanner Master Risott
 Tonnage 2200 Built at Swindland When built 1834
 By whom built _____ Owners Thomson
 Port belonging to London Destined Voyage Samaria
 Surveyed ~~Abroad~~ in Dry Dock Mr King

Original Survey, No. 1 Port of Swindland, Classified N.A.1
Son. 4040, 4803, 5710, ⁶⁵⁸ ~~5710~~

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms <u>good where</u>	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame <u>seen</u>	Masts, Yards, &c.
Spirketting <u>good</u>	Topides	Sails <u>good & sufficient</u>
Plank Shears	Wales	Cables
Waterways	Plank and Treennails <u>good</u> <small>(Outside to the Water's Edge)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, All the present timbers Renewed all the Sheenails from the
 as required by the Instructions, upper to the upper edge of wales, under the wales brought down to
shear 2 Planks in Stowage between the timbers reported
to be good - the ship is in good Condition & may remain

Committee Minute 28th Septe 1841
 Character assigned 10 A 1
Nath. J. Clark

No. 453 Survey held at London Date Sept 14th 1841
 on the Barque Robin Castle Master Sadler
 Tonnage 452 Built at Bristol When built 1819
 By whom built _____ Owners Sadler
 Port belonging to London Destined Voyage Swice Home
 Surveyed ~~Abroad~~ in Dry Dock Mr Ritchie

Original Survey, No. 112 Port of London, Classified A.1
3977, Ply. 537, Son. 1284.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings <u>in a</u>	Transoms <u>good where</u>	Pumps
Lower Deck Beams & Fastenings <u>good</u>	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>fair</u>	Topides	Sails <u>good & suff</u>
Plank Shears <u>State</u>	Wales	Cables
Waterways	Plank and Treennails <u>good there</u> <small>(Outside to the Water's Edge)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, All the present timbers Sheathed with white prepared
 as required by the Instructions, iron plates to 1/2 inch - The Ship is in good
Condition & may remain in service

Committee Minute 29th Septe 1841
 Character assigned 10 A 1
Nath. J. Clark