

REPORT of SURVEY for REPAIRS.

Change of Carcass

No. ¹⁰⁰ Survey held at London Date Sept 1841
 on the Ship Maryles Master Driscoll
 Tonnage 574 Built at Calcutta When built 1802
 By whom built _____ Owners J. R. Ward
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackette Dry Dock

Original Survey, No. 1352, 2075, Dated 1839 5588, Classed A. 1 Outward

Port of London

REPAIRS At the present time bottom examined, copper putshed & the
Wales & upper works caulked
rigging stripped and a general overhaul

Present Condition of the

Decks	Transoms <u>Ships</u>	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame <u>Ships</u>	Capestan
Lower Deck Beams & Fastenings	Topsides <u>Ships</u>	Pumps
Spirkettling	Wales <u>"</u>	Masts, Yards, &c. <u>Ships</u>
Plank Shears	Counter <u>"</u>	Sails
Waterways	Plank & Treennails <u>"</u> (Outside to the Water's Edge)	Cables <u>Sufficient</u>
Hatchway Comings	Rudder <u>"</u>	Anchors No. of
Breasthooks	Copper <u>in 1839</u>	Standing & Running Rigging

General Observations and Opinion Present a very firm appearance no symptoms of weakness
in decay and appears in an efficient state for the safe
conveyance of my & passengers across the Atlantic
of the World and may be considered as fitted A. 1 Outward

The Amount of Fee.....£ 3 : : : is received by me, officer

Committee's Minute 5th October 1841

Character assigned A. 1 Outward

Lloyd's Register
Foundation